

## Case Study – Tram windscreen platform

### Background

No Bolt was contacted by Yarra Trams to help with an access issue they had with regards to the cleaning, replacing and removal of their Tram windscreens.

The windscreens are constantly in need of cleaning, and can be often cracked needing repair work or replacement. Yarra Trams were concerned about a potential fall risk when their designated worker cleaned and removed the windscreens.

### Challenge

A No Bolt Custom Platform was required to protect the employee. It had to transport and hold the fragile windscreen securely when transporting the platform and windscreen to the front of the tram.

Yarra Trams required a solution that provided clear access to the front of varying tram designs. This design needed to be lightweight, so one person could use it.

### Solution

We worked in partnership with Yarra Trams to deliver a solution that was:

- Easy to use
- Compliant
- Strong
- Safe

